








INTERNET CONNECTION FOR TIME CORRECTION.




Note: The suggestion provided may or may not be suitable for your intended application. Please consider this information carefully before incorporating it into your system design. Valcom disclaims any responsibility for accuracy or completeness.

VALCOM 5614 Hollins Road
Roanoke, VA 24019
540-563-2000

**WIRED CLOCK HEAD END
INTERNET TIME SERVER CORRECTION
SCENARIO
2-WIRE DIGITAL**

Revision C



Note: The suggestion provided may or may not be suitable for your intended application. Please consider this information carefully before incorporating it into your system design. Valcom disclaims any responsibility for accuracy or completeness.

VALCOM 5614 Hollins Road
 Roanoke, VA 24019
 540-563-2000

**WIRED CLOCK HEAD END
 INTERNET TIME SERVER CORRECTION
 SCENARIO
 2-WIRE DIGITAL**

Revision C