









NOTE:  
DATA TRANSMIT RATE MUST  
BE SET TO EVERY SECOND.



RELAY MAY BE  
PROGRAMMED TO  
CLOSE AT 2:00AM  
TO SYNCH THE  
CLASS CONNECTION  
OR MULTIPATH SYSTEMS.



Note:

The suggestion provided may or may not be suitable for your intended application. Please consider this information carefully before incorporating it into your system design. Valcom disclaims any responsibility for accuracy or completeness.

**VALCOM**

WIRELESS CLOCK HEAD END  
GPS MASTER CLOCK CORRECTION  
SCENARIO

5614 Hollins Road  
Roanoke, VA 24019  
540-563-2000